

Hawaii Farm Equipment Use Report



March 19, 2018

In Cooperation with the Hawaii Department of Agriculture

Hawaii Field Office · 300 Ala Moana Blvd Suite 7-118· Honolulu, HI 96850 · (800) 804-9514 · www.nass.usda.gov

HAWAII FARM EQUIPMENT FALLS SHORT OF NUMBER DESIRED IN 2018

Farm equipment used by farmers in Hawaii fell short of the number desired, according to a recent survey conducted by USDA National Agricultural Statistics Service (NASS), in cooperation with the Hawaii Department of Agriculture. The Hawaii Farm Equipment Use survey was conducted during the months of February and March, 2018. Farmers in all four counties received the survey, the purpose of which was to determine the use of farm equipment by Hawaiian farmers and their desired number of specific equipment. Vegetable growers reported a need for an additional 505 mechanical harvesters, over the 238 currently in use. The most common piece of equipment found on Hawaii farms was a backpack sprayer.


Hawaii: Types of Farm Equipment, Number Used, Number Desired in addition to Number Used, 2018

TYPE OF EQUIPMENT	NUMBER USED	NUMBER DESIRED (in addition to Number
·		` Used)
Tillage		
Chisel Plow, any size	195	144
Disc Harrow, any size	253	142
Flail Mower, any size	407	303
Field Cultivator		
Non-folding, any size	226	208
Flexible folding, any size	43	83
Row Crop Cultivator		
Non-folding, any size	178	157
Flexible folding, any size	6	45
Walk-behind roto-tiller	697	661
Planting		
Seed drill, any size	132	104
Vegetable planter, any size, mechanical	127	141
vegetable planter, any size, meditambar	121	171
Harvesting		
Root Crop harvester, mounted or drawn, mechanical	46	150
Vegetable harvester, mechanical	238	505
Other Favinment		
Other Equipment	545	200
Farm Wagon Running Gear, with or without box	343	396
Sprayer, mounted or drawn, mechanical Tractor mounted, any size tank	714	362
· •	663	339
Trailer type, any size tank	618	304
Sprayer, self-propelled, any size tank	I I	
Backpack sprayer, any size tank Forklift	5,226	2,807
	668	395
Skid Steer	484	405
ATV/UTV, any size Handcart	2,120	1,898
	3,299	1,985
Telehandler (i.e., Skytrak)	99	158

(continued)

In addition, respondents were asked about easy access to repair for the farm equipment. Over one-third of respondents reported that access to repair was difficult. Reasons given were distance from repair shop, time required to travel to repair shop, cost of transportation, cost of repair, and finding qualified mechanics.

State of Hawaii
Ease of Access to Farm Equipment Repair, 2018



Source: USDA NASS Pacific Region, Hawaii, 2018